Approved For Release 2001/04/20 : 614 PDB 44900187A000700110005-6

SPD 1195-400

FIELD SERVICE AND SUPPORT

ACTIVITY REPORT NO. 19

1 August through 31 August 1960

CMCC Document No. 163x5.121 Copy 7 of 7

(This document contains a total of 6 sheets, including this Title Page.)

DOCUMENT NO.

NO CHANGE IN SLASS. TO

BECCLASSIFIED
CLASS. EMARC. IC: 10 S GO 11

NEAT HE VIEW 10-2

ABTH: Will 10-2

I. INTRODUCTION

This report describes the August 1960 activity for Contracts A-102 and HF-CT-699.

II. CONTRACT A-102

A. Activity Related to Customer A

- 1. Sustaining Engineering
 - a. Improved Recorder Reliability

With approval of Project Headquarters, the Contractor will furnish kits necessary to incorporate the modifications contained in Engineering Change Proposal 9AC into recorders belonging to the Depot and Detachment C. Detachment-B units will not be modified at the present time.

b. Third Local Oscillator Test Specifications

As a result of an engineering investigation, the Contractor reviewed Third Local Oscillator component tolerances and subsequently wrote more stringent test specifications for capsules Z1812 and Z1816. Other capsules are being evaluated.

c. System-3 First Local Oscillator Crystal Specifications

A meeting between the Contractor and representatives of McCoy Electronics Company, manufacturer of the first local oscillator crystals, was held in August to establish more stringent specifications in the manufacture of crystals above the frequency range called out in Mil. Spec. C-3098-B. As a result of this meeting, the Contractor published Specification No. 500356 which covers crystals in the frequency range of

25X1D

d. Customer-A Liaison

25X1A

On 9 August, made a trip to Customer A's local test site to assist in setting up the new electronic shop.

- 2. Repair and Retrofit
 - a. Repair and Retrofit Inventory

The Repair and Retrofit Inventory for August is listed in Table 1.

b. Printed Circuit Board Improvements

The Repair and Retrofit Laboratory is currently evaluating the layout of the printed circuit wiring used in System 3. Some circuit changes have been made to improve the reliability of future units.

- B. Activity Related to Customer C
 - 1. Sustaining Engineering
 - a. Engineering Change Proposal 9AC

All components for the first 10 modification kits called out in Engineering Change Proposal 9AC have been shipped to the Depot.

- 10 (MP 10050MD1) Capstan Drive Assemblies in June
- 10 (MP 10065MD1) Jam Roller Assemblies in August
- 30 Field Service Bulletin 1-19, 3-18

25X1D

25X1D



c. Visit by Contractor Technical Representative

25X1A

engineer in charge at Del Rio,
Texas, visited the plant from 22 through 26 August. The
purpose of his visit was to attend the System-4 briefing
and to participate in certain technical discussions with the
Contractor's in-plant personnel.

d. Activities Common to Customer C and Customer A

The Third Local Oscillator Test Specifications, System-3 First Local Oscillator Crystal Specifications, and Printed Circuit Board Improvements are projects common to Customer C and Customer A. For detailed information, see paragraphs A.1.b., c., and A.2.b., respectively.

2. Repair and Retrofit

The Repair and Retrofit Inventory for August is listed in Table 1.

Approved For Release 2001/04/20: SECRET 0187A000700110005-6
Activity Report No. 19
Page 4

C. Activity Related to Customer D

1. Sustaining Engineering

The Third Local Oscillator Test Specifications, System-3 First Local Oscillator Crystal Specifications, and Printed Circuit Board Improvements are projects which also apply to Customer-D equipment. For detailed information, see paragraphs A.1.b., c., and A.2.b., respectively.

2. Repair and Retrofit

The Repair and Retrofit Inventory for August is listed in Table 1.

III. CONTRACT HF-CT-699

The Call Contract Inventory for August is listed in Table 2.

TABLE 1

REPAIR AND RETROFIT INVENTORY FOR AUGUST 1960

| | Rework Units | D | Rework Units | | | |
|----------|-----------------------|-------------------|------------------|-----------------------|-----------------------|--|
| Customer | Outstanding on 8-1-60 | Units Received | Units Shipped | Units Nonreparable | Backlog on 8-31-60 | |
| | | | | | | |
| Α | 17 | 9 | 8 | 3 | 15 | |
| С | 13 | 18 | 17 | 0 | 14 | |
| D | 0 | 2 | 2 | 0 | 0 | |
| | | | | | | |

TABLE 2

CALL CONTRACT INVENTORY FOR AUGUST 1960

| | | Requested During August | | | Units | Unit |
|----------|---------------------------|-------------------------|---------------------|----------------|------------------------|--------------------|
| Customer | Unit Backlog on 8-1-60 | Production Lists | Total Line Items | Total Units | Delivered in August | Backlog 8-31-60 |
| | | | | | | |
| A | 113 | 1 | 4 | 48 | 53 | 108 |
| С | 326 | 7 | 18 | 1 41 | 114 | 353 |
| D | 0 | 22 | 22 | 128 | 3 | 1 25 |
| | | | | | | |